


**READYPOWER ENGINEERING LTD**  
**LIFTING OPERATION AND LIFTING EQUIPMENT REGULATIONS 1998**

THOROUGH EXAMINATION AND INSPECTION OF LIFTING EQUIPMENT

1) Name and address of owner of equipment	Readypower Engineering Ltd Readypower House. Molly Millars Bridge. Wokingham Berks. RG41 2WY
2) Address at which thorough examination and inspection took place	Readypower Engineering Ltd Derby Yard
3) Type of equipment and nature of power e.g. Scotch derrick-manual; Tower derrick-electric; Rail mounted tower-electric	CASE 988 WHEELED EXCAVATOR ROAD RAILER
4) Date of manufacture of equipment	2000
5) Identification number a) Makers Serial Number b) Owners distinguishing mark or number (if any)	SERIAL No. CGG0129059 ----- PLANT No. FR605
6) Make and type of rated capacity indicator, if required	PROLEC LIFTWATCH LW4
7) Date of last previous thorough examination of the lifting equipment	<b>27<sup>TH</sup> MAY 2009</b>
8) Date of next thorough examination of lifting equipment	<b>11<sup>TH</sup> MAY 2011</b>
9) Safe working load or loads	SEE ATTACHED SCHEDULE
10) Defects noted and alterations or repairs required before equipment is put into service, or which may affect the safety of the machine	None
11) Repairs required (if any) either:  a) Immediately, or b) Within a specified time (to be stated)  To enable the lifting machine to continue to be used with safety.  (If none enter "None")	None
12) In relation to a thorough examination of lifting equipment, whether it is a thorough examination: - <input type="checkbox"/> (i) Within an interval of 6 months under regulation 9(3)(a)(i) <input checked="" type="checkbox"/> (ii) Within an interval of 12 months under regulation 9(3)(a)(ii) <input type="checkbox"/> (iii) In accordance with an examination scheme under regulation 9(3)(a)(iii) <input type="checkbox"/> (iv) After the occurrence of exceptional circumstances under regulation 9(3)(a)(iv) (Please tick box) And that the lifting equipment would be safe to operate.	

I hereby certify that the lifting equipment described in this report, including the auxiliary lifting point / basket work restraint anchor points was tested and thoroughly examined by D. Sim on **12<sup>th</sup> May 2010** and that the above particulars are correct.

Signature



W.D. Rosser  
Service Manager

Name and address of person, company or association by whom the person conducting the thorough examination is employed:

Readypower Engineering Ltd  
Readypower House.  
Molly Millars Bridge  
Wokingham  
Berks, RG41 2WY