FR/003

# READYPOWER ENGINEERING LTD

## LIFTING OPERATION AND LIFTING EQUIPMENT REGULATIONS 1998

THOROUGH EXAMINATION AND INSPECTION OF LIFTING EQUIPMENT

| | |
|---|---|
| 1) Name and address of owner of equipment | Readypower Engineering Ltd<br>Readypower House<br>Molly Millars Bridge. Bracknell<br>Berkshire. RG41 2WY |
| 2) Address at which thorough examination and inspection took place | Readypower Engineering Ltd<br>Longshot Lane<br>Bracknell<br>Berkshire<br>RG12 1RL |
| 3) Type of equipment and nature of power e.g. Scotch derrick-manual; Tower derrick-electric; Rail mounted tower-electric | KOMATSU PW410 WHEELED EXCAVATOR ROAD RAILER |
| 4) Date of manufacture of equipment | 1994 |
| 5) Identification number<br>a) Makers Serial Number<br>b) Owners distinguishing mark or number (if any) | SERIAL No. 21D0004375<br>----------<br>PLANT No. FR1003 |
| 6) Make and type of rated capacity indicator, if required | NONE |
| 7) Date of last previous thorough examination of the lifting equipment | 13TH MARCH 2006 |
| 8) Date of next thorough examination of lifting equipment | 1ST MAY 2008 |
| 9) Safe working load or loads | SEE ATTACHED SCHEDULE |
| 10) Defects noted and alterations or repairs required before equipment is put into service, or which may affect the safety of the machine | NONE |
| 11) Repairs required (if any) either:<br>a) immediately, or<br>b) within a specified time (to be stated)<br>to enable the lifting machine to continue to be used with safety.<br>(if none enter "None") | NONE |

12) In relation to a thorough examination of lifting equipment, whether it is a thorough examination:-

- ☐ (i) within an interval of 6 months under regulation 9(3)(a)(i)
- ☑ (ii) within an interval of 12 months under regulation 9(3)(a)(ii)
- ☐ (iii) in accordance with an examination scheme under regulation 9(3)(a)(iii)
- ☐ (iv) after the occurrence of exceptional circumstances under regulation 9(3)(a)(iv)

(please tick box)
and that the lifting equipment would be safe to operate.

I hereby certify that the lifting equipment described in this report was tested and thoroughly examined by Service Engineer S. Limb on 2ND MAY 2007……. and that the above particulars are correct.

Signature

Name and address of person, company or association by whom the person conducting the thorough examination is employed:

W D ROSSER
Service Manager
Readypower Engineering Ltd
Readypower House
Molly Millars Bridge
Wokingham
Berks. RG41 2WY