

## LIFTING OPERATION AND LIFTING EQUIPMENT REGULATIONS 1998

## THOROUGH EXAMINATION AND INSPECTION OF LIFTING EQUIPMENT

|   |   |
|---|---|
| 1) Name and address of owner of equipment   | Readypower Engineering Ltd<br>Readypower House<br>Molly Millars bridge,<br>Wokingham<br>Berkshire, RG41 2WY |
| 2) Address at which thorough examination and inspection took place  | Readypower Engineering Ltd<br>Station Road<br>Kings Langley<br>Herts<br>WD4 8LF                             |
| 3) Type of equipment and nature of power<br>e.g. Scotch derrick-manual; Tower derrick-electric; Rail mounted tower-electric   | ROAD RAIL ACCESS UNIT   |
| 4) Date of manufacture of equipment   | 2008  |
| 5) Identification number<br>a) Makers Serial Number<br>b) Owners distinguishing mark or number (if any)   | Genie Access Railer<br>SERIAL No Z6008-9583<br>-----<br>PLANT No. FR1335                                    |
| 6) Make and type of rated capacity indicator, if required   | NONE  |
| 7) Date of last previous thorough examination of the lifting equipment  | <b>13<sup>TH</sup> MARCH 2011</b>   |
| 8) Date of next thorough examination of lifting equipment   | <b>27<sup>TH</sup> MARCH 2012</b>   |
| 9) Safe working load or loads   | 300kg   |
| 10) Defects noted and alterations or repairs required before equipment is put into service, or which may affect the safety of the machine   | None  |
| 11) Repairs required (if any) either:<br><br>a) immediately, or<br>b) within a specified time (to be stated)<br><br>to enable the lifting machine to continue to be used with safety.<br><br>(if none enter "None")   | None  |
| 12) In relation to a thorough examination of lifting equipment, whether it is a thorough examination:-<br><input checked="" type="checkbox"/> (i) within an interval of 6 months under regulation 9(3)(a)(i)<br><input type="checkbox"/> (ii) within an interval of 12 months under regulation 9(3)(a)(ii)<br><input type="checkbox"/> (iii) in accordance with an examination scheme under regulation 9(3)(a)(iii)<br><input type="checkbox"/> (iv) after the occurrence of exceptional circumstances under regulation 9(3)(a)(iv) (please tick box)<br>and that the lifting equipment would be safe to operate. |   |

I hereby certify that the lifting equipment described in this report, including the auxiliary lifting point / basket work restraint anchor points was tested and thoroughly examined by Service Engineer Simon Purnell on **28<sup>TH</sup> September 2011 2011** and that the above particulars are correct.

Signature


W D Rosser  
Service Manager

Name and address of person, company or association by whom the person conducting the thorough examination is employed:

Readypower Engineering Ltd  
Readypower House  
Molly Millars Bridge  
Wokingham  
Berks. RG41 2WY