

READYPOWER ENGINEERING LTD

LIFTING OPERATION AND LIFTING EQUIPMENT REGULATIONS 1998

THOROUGH EXAMINATION AND INSPECTION OF LIFTING EQUIPMENT

1) Name and address of owner of equipment	Readypower Engineering Ltd Readypower House Molly Millars bridge. Wokingham Berkshire. RG41 2WY
2) Address at which thorough examination and inspection took place	Readypower Engineering Ltd Ready power House Molly Millars Bridge. Wokingham Berkshire. RG41 2WY
3) Type of equipment and nature of power e.g. Scotch derrick-manual; Tower derrick-electric; Rail mounted tower-electric	KOMATSU PW410 WHEELED EXCAVATOR ROAD RAILER
4) Date of manufacture of equipment	1994
5) Identification number	SERIAL No. 21D0004186
a) Makers Serial Number	-----
b) Owners distinguishing mark or number (if any)	PLANT No. FR1001
6) Make and type of rated capacity indicator, if required	NONE
7) Date of last previous thorough examination of the lifting equipment	14 TH NOVEMBER 2006
8) Date of next thorough examination of lifting equipment	30 TH OCTOBER 2008
9) Safe working load or loads	1 TONNE
10) Defects noted and alterations or repairs required before equipment is put into service, or which may affect the safety of the machine	NONE
11) Repairs required (if any) either: a) immediately, or b) within a specified time (to be stated) to enable the lifting machine to continue to be used with safety. (if none enter "None")	NONE
12) In relation to a thorough examination of lifting equipment, whether it is a thorough examination:-	
<input type="checkbox"/> (i) within an interval of 6 months under regulation 9(3)(a)(i) <input checked="" type="checkbox"/> (ii) within an interval of 12 months under regulation 9(3)(a)(ii) <input type="checkbox"/> (iii) in accordance with an examination scheme under regulation 9(3)(a)(iii) <input type="checkbox"/> (iv) after the occurrence of exceptional circumstances under regulation 9(3)(a)(iv) (please tick box) and that the lifting equipment would be safe to operate.	

I hereby certify that the lifting equipment described in this report was tested and thoroughly examined by Engineer D. Sim on 31ST OCTOBER 2007 and that the above particulars are correct.

Signature 

W.D. ROSSER
Service Manager

Name and address of person, company or association by whom the person conducting the thorough examination is employed:

Readypower Engineering Ltd
Readypower House
Molly Millars Bridge
Wokingham
Berks. RG41 2WY