



**REPORT OF A THOROUGH 12 MONTHLY EXAMINATION
INCLUDING LIFTING ATTACHMENTS**

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

| | | | | | |
|--|---------------------|---|--|--|--|
| Date of thorough Examination: 01/11/2011 | | Date Of Report: 01/11/2011 | | Report Number: FR655/01 | |
| Name and Address of Employer for whom the Thorough examination was made Readypower Readypower House Molly Millers Bridge Wokingham Berkshire RG41 2WY | | | Address of premises at which the examination was made. Readypower Cwmbran | | |
| Description and Identification of the Equipment: | | Safe Working Load(s): | Date of Manufacture if Known: | Date of last thorough examination | |
| <i>Make</i> | : <i>Case</i> | <i>Check valves & RCI Prolec LW5 fitted refer to lift chart supplied.</i> | 2004 | 25/10/2010 | |
| <i>Model</i> | : <i>CX135SR</i> | | | | |
| <i>Serial Number</i> | : <i>DCH13U0327</i> | | | | |
| <i>Stock Number</i> | : <i>FR655</i> | | | | |
| <i>Number of Components</i> | : | | | | |
| <i>Delete as necessary</i> | | <i>Delete as necessary</i> | | | |
| Is this the first examination after installation <i>No</i> | | <i>Was the examination carried out:</i> | | | |
| | | <i>Within an interval of 6 Months?</i> | | <i>No</i> | |
| Has the equipment been installed correctly <i>Yes</i> | | <i>Within an interval of 12 Months?</i> | | <i>Yes</i> | |
| | | <i>After the occurrence of exceptional circumstances?</i> | | <i>No</i> | |
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (if none state NONE) | | | | | |
| <i>None</i> | | | | | |
| Is the above a defect which is of immediate danger to persons? | | | | | |
| <i>No</i> | | | | | |
| Is the above defect, which is not yet but could be become a danger to persons? (If yes state the date by when) | | | | | |
| <i>No</i> | | | | | |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: | | | | | |
| <i>None</i> | | | | | |
| Particulars of any tests carried out as a part of the examination: (if none state NONE) | | | | | |
| <i>Visual Inspection Only</i> | | | | <i>Yes</i> | |
| <i>Brake Test</i> | | | | <i>Yes</i> | |
| <i>Lift Test</i> | | | | <i>Yes</i> | |
| <i>Machine Hrs</i> | | | | <i>2671</i> | |
| IS THIS APPLIANCE OR ACCESSORY SAFE TO OPERATE? | | | | | |
| Yes | | | | | |
| Name of person making this report: | | Name of this person authenticating this report: | | Latest date by which next thorough examination must be carried out: | |
| Print Name: Chris Fitzgerald | | Print Name: Jon Curtis | | 31/10/2012 | |
| Signature: <i>C Fitzgerald</i> | | Signature: <i>J Curtis</i> | | | |
| Name and Address of employer making and authenticating this report | | | | | |
| <i>Fitzgerald plant services Limited</i> | | | | | |
| Avondale Way, Avondale Ind. Est., Cwmbran, South Wales, NP44 1TS | | | | | |